




#### Radiography-how it works?




If you use very simple device like X-ray tube and connect it with the high voltage generator (very high voltage about 300 000 volts) in the little spot on the anode small miracle appears...




Electrons in the field of nucleus producing X-rays!




With bremstrahlung and characteristic radiation with that spectrum we can see almost everything inside the specimen of building material




### Medical Computed Tomography






Moreover we can reconstuct 3D model of surface...

Using medical CT- Computed tomography, we can imaging object slice by slice




..or even internal arrangement of fibers


# Microtomography







Fibers




Crack 8,9 microns wide

3D reconstruction of concrete sample with resolution 3,8 microns

# Microtomography Surface Pores Fibers Pores grouped by volume according color table


# Microtomography- statistics and calculations



#### Magnetic Resonance- methodology


- Position the sample in the magnet
- We give an RF signal to transmit energy to protons
- We use the gradient field variables
- We pick up the signal transmitted by the protons that capture the stored energy
- We process data to obtain the image

receive




transmit


# Magnetic Resonance- 3D reconstruction of surface



# Magnetic Resonance- water distribution in the specimen



#### Neutron Activation Analysis



Neutron activation analysis (NAA) is one of the most precise non-destructive methods for determining the concentrations of elements in any kind of materials. It is extremely interesting to use that method for identify trace or rare earth elements in building materials. The method is based on nuclei activation as a result of the collision with neutron and therefore requires a very efficient source of neutrons like nuclear reactor.

#### Neutron Activation Analysis

Estimated Detection limits for INAA using decay gamma rays (assuming irradiation in a reactor neutron flux of  $1x10^{13}$  n cm<sup>-2</sup> s<sup>-1</sup>)

Sensitivity (picograms)	Elements
1	Dy, Eu
1–10	In, Lu, Mn
10–100	Au, Ho, Ir, Re, Sm, W
100–1000	Ag, Ar, As, Br, Cl, Co, Cs, Cu, Er, Ga, Hf, I, La, Sb, Sc, Se, Ta, Tb, Th, Tm, U, V, Yb
1000-104	Al, Ba, Cd, Ce, Cr, Hg, Kr, Gd, Ge, Mo, Na, Nd, Ni, Os, Pd, Rb, Rh, Ru, Sr, Te, Zn, Zr
10 <sup>4</sup> –10 <sup>5</sup>	Bi, Ca, K, Mg, P, Pt, Si, Sn, Ti, Tl, Xe, Y
105-106	F, Fe, Nb, Ne
10 <sup>7</sup>	Pb, S

